


**OFFICE OF THE ASSISTANT ENGINEER,
BOSE (R&B) SECTION, CUTTACK**

TO WHOM IT MAY CONCERNED

Letter No - 100 dt 11/12/2024

As per Personal request of the concerned Institute authority ,I have inspected the site of the above building "Sri Sathya Sai School, KVK road, Cuttack on Dtd 11.12.2024 & found that the building is a Frame structure building (G+2) , there is no settlement & cracks developed in the structure . I have seen that the building is well maintained properly and in my impression the building is quite safe enough to run the said school


11/12/24
Assistant Engineer
BOSE (R&B) Section
Cuttack.